





MICROMAR 8




CZ D E F
GB I P S

FD4340000MC


- A) CZ Měřicí síla / D Messkraft / E fuerza de medición
F force de mesure / GB measuring force / I forza di misura
P força de medição / S Inställning mättryck



- B) CZ Zdvih náběhu / D Vorhub / E precarrera
F précourse / GB pre-travel / I precorsa
P pré-percurso / S Inställning förrörelse



- C) (CZ) Zdvih přeběhu / (D) Überhub / (E) sobrecarrera
 (F) surcourse / (GB) overtravel / (I) oltrecorsa
 (P) fora de curso / (S) Inställning överrörelse



- D) (CZ) nulování / (D) Nullabgleich / (E) puesta a cero
 (F) mise à zéro / (GB) zero-setting / (I) azzeramento
 (P) zeramento / (S) nollställning

